


MEASUREMENT SPECS FOR MEN BOXER



1. Measurement Specs

Measurement Point	S	M	L	XL
Waist relaxed	62	62	68	71
Front rise(inc. waistband)	20	20	21	21
Back rise(inc. waistband)	22	24	26	28
Side length excl w.b	20	21	22	23
W.b. height	4	4	4	4
Crotch	10	10	10.5	10.5
Inside leg	4	5	6	7

2. Printing Method (Basically)


A. Pigment Printing (Water based printing)

Mainly printed on the light colour fabric, please see examples below:



B. Plastisol Printing (Rubber Printing)

Mainly printed on the dark colour fabric, please see examples below:



C. Discharge Printing

Mainly printed on the dark colour fabric, but the appearance is similar the water based printing, please see examples below:



D. Flocking

Stereoeffect, please see examples below:

